

CHRYSLER B1858: DRIVER WINDOW POSITION SENSOR POWER SUPPLY LOW

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$80-\$400
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chrysler B1858 Code Mean?

When the Driver Window Hall Sensor Supply circuit falls below 0.8 volt for over 480 ms., this code will set.

What Are The Potential Causes Of The Chrysler B1858 Code?

- Low battery voltage
- Driver window hall sensor supply circuit faulty wiring
- Driver window motor shorted
- Driver door module (DDM)

Reference Sources

[Chrysler B1858](#), DTCDECODE.