

CHRYSLER B1859: DRIVER WINDOW POSITION SENSOR POWER SUPPLY HIGH

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$80-\$400
Can I Still Drive?	:	Yes

What Does The Chrysler B1859 Code Mean?

Whenever the power is turned off to the module and it goes from being awake to sleep mode. When the Driver Window Hall Sensor Supply circuit is above 1.5 volts for over 15 ms. and the power to the module has been turned off, this code will set

What Are The Potential Causes Of The Chrysler B1859 Code?

- (Q305) DRIVER WINDOW HALL SENSOR SUPPLY CIRCUIT SHORTED TO VOLTAGE
- DRIVER DOOR MODULE (DDM)

Reference Sources

[Chrysler B1859](#), DTCDECODE.