

CHRYSLER B1889: POWER LIFTGATE PINCH SENSOR 1 CIRCUIT HIGH

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$500
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chrysler B1889 Code Mean?

The Power Liftgate Module has detected the Left Liftgate Pinch Sensor circuit voltage is above 4.8 volts for over 10 seconds.

What Are The Potential Causes Of The Chrysler B1889 Code?

- Logic ground circuit faulty wiring
- Left pinch sensor signal circuit faulty wiring
- Left liftgate pinch sensor
- Power liftgate module (PLGM)

Reference Sources

[Chrysler B1889](#), DTCDECODE.