

CHRYSLER B1948: POWER LIFTGATE PINCH SENSOR 2 CIRCUIT HIGH

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$500
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chrysler B1948 Code Mean?

The Power Liftgate Module has detected the Right Liftgate Pinch Sensor circuit voltage is above 9.5 volts for over 10 seconds.

What Are The Potential Causes Of The Chrysler B1948 Code?

- Logic ground faulty wiring
- Right pinch sensor signal circuit faulty wiring
- Right liftgate pinch sensor
- Power liftgate module (PLGM)

Reference Sources

[Chrysler B1948](#), DTCDECODE.