

CHRYSLER B1E2E: 3RD ROW SEAT LEFT BACKREST SWITCH CIRCUIT LOW

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chrysler B1E2E Code Mean?

This DTC is set when the Folding Seat Module (FSM) detects the (P282) Left Seat Recliner Switch MUX circuit voltage is below .9 volts.

What Are The Potential Causes Of The Chrysler B1E2E Code?

- Left power rear folding seat recliner switch
- (P282) left seat recliner switch mux circuit short to (P281) seat recliner switch return
- (P282) left seat recliner switch mux circuit short to ground
- Folding seat module (FSM)

Reference Sources

[Chrysler B1E2E](#), DTCDECODE.