

CHRYSLER B1E30: 3RD ROW SEAT LEFT BACKREST SWITCH STUCK FORWARD

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

What Does The Chrysler B1E30 Code Mean?

When the Folding Seat Module (FSM) senses the Left Switch FORWARD switch position input for longer than 50 seconds, this code will set.

What Are The Potential Causes Of The Chrysler B1E30 Code?

- Left power rear folding seat recliner switch
- (p282) left seat recliner switch mux circuit short to (p281) seat recliner switch return
- (p282) left seat recliner switch mux circuit short to ground
- Folding seat module (FSM)

Reference Sources

[Chrysler B1E30](#), DTCDECODE.