

## CHRYSLER B1E4F: 3RD ROW SEAT LEFT STOW/TAILGATE POSITION SENSOR CIRCUIT HIGH

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Chrysler B1E4F Code Mean?

If during motor operation the sensor voltage is not within a specified range this code will set.

### What Are The Potential Causes Of The Chrysler B1E4F Code?

- (P318) left seat stow position sensor circuit shorted to voltage
- Left power rear folding seat stow motor
- Folding seat module (FSM)

### Reference Sources

[Chrysler B1E4F](#), DTCDECODE.