

CHRYSLER B2101: IGNITION RUN/START INPUT LOW

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$400
Can I Still Drive?	:	Yes

What Does The Chrysler B2101 Code Mean?

The Totally Integrated Power Module (TIPM) has detected the ignition switch input voltage below a calibrated value.

What Are The Potential Causes Of The Chrysler B2101 Code?

- (F20) fused ignition switch output (run-start) circuit shorted to ground
- Wireless ignition node (WIN)
- TIPM

Reference Sources

[Chrysler B2101](#), DTCDECODE.