

## CHRYSLER B2298: RAIN SENSOR OVER TEMPERATURE

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$200
Can I Still Drive?	:	Yes

### What Does The Chrysler B2298 Code Mean?

With the ignition on. The Light Rain Sensing Module (LRSM) detects that the internal module temperature is higher than expected

### What Are The Potential Causes Of The Chrysler B2298 Code?

- HIGH AMBIENT TEMPERATURE
- LIGHT RAIN SENSING MODULE (LRSM)

### Reference Sources

[Chrysler B2298](#), DTCDECODE.