CHRYSLER C1008: BRAKE FLUID LEVEL CIRCUIT HIGH			
		OVERVIEW	
Severity	:	Medium	
DIY Difficulty Level	:	Intermediate	
Repair Cost	:	\$50-\$120	
Can I Still Drive?	:	Yes	

## What Does The Chrysler C1008 Code Mean?

When the Totally Integrated Power Module (TIPM) detects the Brake Fluid Level Circuit voltage is greater than expected for more than five seconds.

## What Are The Potential Causes Of The Chrysler C1008 Code?

- (B20) BRAKE FLUID LEVEL SWITCH SENSE CIRCUIT OPEN
- (B20) BRAKE FLUID LEVEL SWITCH SENSE CIRCUIT SHORTED TO BATTERY VOLTAGE
- (P37) SWITCH RETURN CIRCUIT OPEN
- BRAKE FLUID LEVEL SWITCH
- TOTALLY INTEGRATED POWER MODULE (TIPM)

## **Reference Sources**

Chrysler C1008, DTCDECODE.

