

CHRYSLER C1008: BRAKE FLUID LEVEL CIRCUIT HIGH

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$120
Can I Still Drive?	:	Yes

What Does The Chrysler C1008 Code Mean?

When the Totally Integrated Power Module (TIPM) detects the Brake Fluid Level Circuit voltage is greater than expected for more than five seconds.

What Are The Potential Causes Of The Chrysler C1008 Code?

- (B20) BRAKE FLUID LEVEL SWITCH SENSE CIRCUIT OPEN
- (B20) BRAKE FLUID LEVEL SWITCH SENSE CIRCUIT SHORTED TO BATTERY VOLTAGE
- (P37) SWITCH RETURN CIRCUIT OPEN
- BRAKE FLUID LEVEL SWITCH
- TOTALLY INTEGRATED POWER MODULE (TIPM)

Reference Sources

[Chrysler C1008](#), DTCDECODE.