

CHRYSLER C1073: ABS PUMP MOTOR CONTROL CIRCUIT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$500-\$800
Can I Still Drive?	:	Yes

What Does The Chrysler C1073 Code Mean?

With the ignition on. The ABM detects low pump motor feedback voltage with actuation of the pump motor relay

What Are The Potential Causes Of The Chrysler C1073 Code?

- BLOWN PUMP FUSE
- HIGH RESISTANCE IN B+ CIRCUITS
- HIGH RESISTANCE IN GROUND CIRCUITS
- INTEGRATED CONTROL UNIT (ICU)

Reference Sources

[Chrysler C1073](#), DTCDECODE.