

CHRYSLER C1508: LEFT REAR TIRE PRESSURE TRIGGER MODULE PERFORMANCE

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$100
Can I Still Drive?	:	No

What Does The Chrysler C1508 Code Mean?

The Wireless Ignition Node (WIN) will monitor the messages from each Tire Pressure Monitoring (TPM) Transponder over the LIN bus. If any of the messages are not received, or are received other than as expected, a DTC will set. When the condition is corrected, or is no longer detected, as acknowledged via a LIN bus message, the WIN will reset the appropriate TPM Transponder fault status.

What Are The Potential Causes Of The Chrysler C1508 Code?

- Intermittent performance DTC
- Left rear tire pressure monitoring (TPM) transponder
- Wireless ignition node (WIN)

Reference Sources

[Chrysler C1508](#), DTCDECODE.