

CHRYSLER C150A: LEFT FRONT TIRE PRESSURE TRIGGER MODULE VOLTAGE HIGH

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$100
Can I Still Drive?	:	No

What Does The Chrysler C150A Code Mean?

Continuously. The Wireless Ignition Node (WIN) receives a message from the Tire Pressure Monitoring (TPM) Transponder indicating that an over voltage condition has been detected

What Are The Potential Causes Of The Chrysler C150A Code?

- INTERMITTENT PERFORMANCE DTC
- (F943) FUSED IGNITION SWITCH OUTPUT (RUN) CIRCUIT OPEN OR HIGH RESISTANCE
- (Z904) GROUND CIRCUIT(S) OPEN OR HIGH RESISTANCE
- LEFT FRONT TIRE PRESSURE MONITORING (TPM) TRANSPONDER
- WIRELESS IGNITION NODE (WIN)

Reference Sources

[Chrysler C150A](#), DTCDECODE.