

CHRYSLER C151C: TIRE PRESSURE SENSORS MISSING

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$100
Can I Still Drive?	:	No

What Does The Chrysler C151C Code Mean?

When installing a new Tire Pressure Monitoring (TPM) Module, the module is programed with universal IDs for the Tire Pressure Monitoring (TPM) Sensors. The TPM Module must be programmed with the correct TPM Sensor ID's.

What Are The Potential Causes Of The Chrysler C151C Code?

- NON-FCC COMPLIANT COMPONENTS
- INCORRECT TIRE PRESSURE MONITORING (TPM) SENSOR ID(S)
- TIRE PRESSURE MONITORING (TPM) SENSOR

Reference Sources

[Chrysler C151C](#), DTCDECODE.