

## CHRYSLER C15C1: EPS MECHANICAL PERFORMANCE

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$320-\$1000
Can I Still Drive?	:	Yes

### What Does The Chrysler C15C1 Code Mean?

Electric Power Steering (EPS) Module detects high friction in the steering system when requesting a motor torque change and rotor positioning is not responding within two seconds.

### What Are The Potential Causes Of The Chrysler C15C1 Code?

- Suspension damage or mechanical failure
- Steering gear improperly installed, damaged or mechanical failure
- Electric power steering (EPS) module

### Reference Sources

[Chrysler C15C1](#), DTCDECODE.