

CHRYSLER C15D8: MISMATCH TIRE SIZE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$80-\$400
Can I Still Drive?	:	No

What Does The Chrysler C15D8 Code Mean?

Module detects that the tire size on the vehicle is greater the 10% of the programed size.

What Are The Potential Causes Of The Chrysler C15D8 Code?

- INCORRECT TIRE SIZE PROGRAMED INTO BODY CONTROL MODULE (BCM)
- INCORRECT TIRE SIZE PROGRAMED INTO ANTILOCK BRAKE SYSTEM (ABS)
- ANTILOCK BRAKE SYSTEM (ABS) DTCS PRESENT
- WRONG TIRE SIZE INSTALLED ON VEHICLE

Reference Sources

[Chrysler C15D8](#), DTCDECODE.