CHRYSLER C15DB: EPS DISABLED OVERVIEW Severity : Medium DIY Difficulty Level : Intermediate Repair Cost : \$320-\$1000 Can I Still Drive? : Yes

What Does The Chrysler C15DB Code Mean?

DTC C15C1-00 or DTC C2217-00 has set multiple times.

What Are The Potential Causes Of The Chrysler C15DB Code?

Electric Power Steering (Eps) Module

Reference Sources

Chrysler C15DB, DTCDECODE.

