

CHRYSLER C220B: ABS ACC NOT CALIBRATED

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$700-\$800
Can I Still Drive?	:	Yes

What Does The Chrysler C220B Code Mean?

Anti-lock Brake System (ABS) Module and Hydraulic Control Unit (HCU) do not match. ABS analog valves are not calibrated.

What Are The Potential Causes Of The Chrysler C220B Code?

- Anti-lock brake system (ABS) module
- Hydraulic control unit (HCU)

Reference Sources

[Chrysler C220B](#), DTCDECODE.