



CHRYSLER P1491: RADIATOR FAN CONTROL RELAY CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	 Medium
DIY Difficulty Level	:	 Intermediate
Repair Cost	:	\$30-\$120
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chrysler P1491 Code Mean?

Key on or engine running; system voltage over 10.5v, and the PCM detected an unexpected voltage condition on the Radiator Fan Control Relay circuit during the CCM test period.

What Are The Potential Causes Of The Chrysler P1491 Code?

- Radiator fan control relay circuit is open or shorted to ground
- Radiator fan control relay circuit is open (test power to IGN)
- Radiator fan control relay is damaged or has failed
- PCM has failed

Reference Sources

[Chrysler P1491](#), DTCDECODE.