

## CHRYSLER P1501: VEHICLE SPEED SENSOR NO. 1/2 DRIVE WHEEL CORRELATION

### OVERVIEW

|                      |   |                         |
|----------------------|---|-------------------------|
| Severity             | : | <div>High</div>         |
| DIY Difficulty Level | : | <div>Intermediate</div> |
| Repair Cost          | : | \$100-\$350             |
| Can I Still Drive?   | : | No                      |

### What Does The Chrysler P1501 Code Mean?

Engine is running and vehicle is moving. Speed control is learned and the speed control is trying to be activated. If the PCM recognizes the rear wheel speed is greater than the front wheel speed, this DTC will set.

### What Are The Potential Causes Of The Chrysler P1501 Code?

- Other active Bus or Communication DTCs
- Incorrect tire circumference
- PCM has failed

### Reference Sources

[Chrysler P1501](#), DTCDECODE.