

What Does The Chrysler P1622 Code Mean?

The O2 Sensor Reference Signal voltage is above 3.7 volts for 9.0 seconds.

What Are The Potential Causes Of The Chrysler P1622 Code?

- O2 SENSOR RETURN CIRCUIT SHORTED TO VOLTAGE
- O2 SENSOR RETURN CIRCUIT OPEN/HIGH RESISTANCE
- OXYGEN (O2) SENSOR
- POWERTRAIN CONTROL MODULE (PCM)

Reference Sources

<u>Chrysler P1622</u>, DTCDECODE.

