

CHRYSLER P1652: SERIAL COMMUNICATION LINK MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$300
Can I Still Drive?	:	No

What Does The Chrysler P1652 Code Mean?

Engine started; and after the TCM did not detect any signals on the Serial Communication Line for more than 20 seconds. Note: Due to the integration of the PCM and TCM, Bus communication between the modules is internal.

What Are The Potential Causes Of The Chrysler P1652 Code?

- TCM cannot communicate with the Instrument Cluster (MIC)
- TCM cannot communicate with the Powertrain Control Module
- PCM/TCM is damaged or it has an internal failure

Reference Sources

[Chrysler P1652](#), DTCDECODE.