

## CHRYSLER P1790: FAULT IMMEDIATELY AFTER SHIFT

### OVERVIEW

|                      |   |              |
|----------------------|---|--------------|
| Severity             | : | High         |
| DIY Difficulty Level | : | Advanced     |
| Repair Cost          | : | \$300-\$1000 |
| Can I Still Drive?   | : | No           |

### What Does The Chrysler P1790 Code Mean?

This DTC is not stored alone. It is stored if a Gear Ratio DTC is detected immediately after shift. The existence of DTC P1790 indicates a mechanical or hydraulic (not electrical) related problem. It should be noted, however, that all mechanical problems don't necessarily result in DTC P1790. When this DTC exists, diagnosing the system should be based on the associated DTC and only mechanical causes should be considered.

### What Are The Potential Causes Of The Chrysler P1790 Code?

Other Dtc Is Present

### Reference Sources

[Chrysler P1790](#), DTCDECODE.