

CHRYSLER P1861: SIPHON LINE DISCONNECTED

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$1000
Can I Still Drive?	:	Yes

What Does The Chrysler P1861 Code Mean?

Ignition on. PCM compares the primary tank level with the secondary tank level. If the PCM detects the primary side is lower than the secondary side, by a calibrated amount, the DTC will set

What Are The Potential Causes Of The Chrysler P1861 Code?

- Damage to fuel tank
- Fuel level signal circuit is open or shorted to ground
- Ground circuit is open
- Internal tank components or siphon hose damaged
- Fuel level Sensor has failed

Reference Sources

[Chrysler P1861](#), DTCDECODE.