

## CHRYSLER U1158: LOST COMMUNICATION WITH SATELLITE VIDEO RECEIVER (SDARV)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

### What Does The Chrysler U1158 Code Mean?

Bus messages not received from the Satellite Video Receiver (SDARV) for approximately two to five seconds.

### What Are The Potential Causes Of The Chrysler U1158 Code?

- Can bus circuits open or shorted
- DTCS related to battery voltage, ignition, or vin messages
- Satellite video receiver power and ground
- TIPM not configured correctly
- Satellite video receiver
- Module that set the DTC

### Reference Sources

[Chrysler U1158](#), DTCDECODE.