

## CHRYSLER U1190: LOST COMMUNICATION WITH HUMIDITY SENSOR

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Chrysler U1190 Code Mean?

The Body Control Module (BCM) does not receive LIN Bus messages from the Humidity Sensor for greater than three seconds.

### What Are The Potential Causes Of The Chrysler U1190 Code?

- Run relay control circuit open or shorted to ground
- Ground circuit open
- LIN bus circuit open
- Humidity sensor

### Reference Sources

[Chrysler U1190](#), DTCDECODE.