

Chrysler U1407: Implausible Engine Torque Request Signal Received

OVERVIEW

Severity

:

Medium

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$75-\$200

Can I Still Drive?

:

Yes

What Does The Chrysler U1407 Code Mean?

Continuously with the ignition on, one valid CAN ID received at least once, and no U0002-CAN Bus Off Performance DTC present. When the TCM detects an incorrect CAN ID from the ECM/PCM.

What Are The Potential Causes Of The Chrysler U1407 Code?

- BCM CAN BUS DTCS present
- ECM/PCM DTCS present
- Transmission control module (TCM)

Reference Sources

[Chrysler U1407](#), DTCDECODE.