

Chrysler U140A: Implausible Right Front Wheel Speed Signal Received

OVERVIEW

Severity

:

High

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$100-\$350

Can I Still Drive?

:

No

What Does The Chrysler U140A Code Mean?

Continuously with the ignition on, one valid CAN ID received at least once, and no [U0002](#)-CAN Bus Off Performance DTC present. When the TCM detects an incorrect CAN ID from the ABS control module.

What Are The Potential Causes Of The Chrysler U140A Code?

- BCM CAN BUS DTCS present
- ABS control module DTCS present
- Transmission control module (TCM)

Reference Sources

[Chrysler U140A](#), DTCDECODE.