OPEN OVERVIEW		
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$450
Can I Still Drive?	:	Yes

What Does The Dodge B1078 Code Mean?

With the ignition on. With the Rear Blower Motor off. When the Totally Integrated Power Module (TIPM) detects a low condition

What Are The Potential Causes Of The Dodge B1078 Code?

- (L124) REAR BLOWER MOTOR RELAY CONTROL CIRCUIT OPEN
- (W24) COIL RELAY SUPPLY CIRCUIT OPEN
- (L124) REAR BLOWER MOTOR RELAY CONTROL CIRCUIT SHORTED TO GROUND
- (W24) COIL RELAY SUPPLY CIRCUIT SHORTED TO GROUND
- REAR BLOWER MOTOR RELAY
- TOTALLY INTEGRATED POWER MODULE (TIPM)

Reference Sources

Dodge B1078, DTCDECODE.

