

DODGE B10BE: CONDENSER FAN CONTROL CIRCUIT LOW

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$450-\$900
Can I Still Drive?	:	Yes (Short-term only)

What Does The Dodge B10BE Code Mean?

With the ignition on. Battery voltage greater than 10.4 volts. If the Totally Integrated Power Module (TIPM) detects a shorted low condition in the (C123) Condenser Fan Control circuit this DTC will set.

What Are The Potential Causes Of The Dodge B10BE Code?

- (C123) condenser fan control output circuit shorted to ground
- Condenser fan motor
- TIPM

Reference Sources

[Dodge B10BE](#), DTCDECODE.