

DODGE B10BF: CONDENSER FAN CONTROL CIRCUIT HIGH

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$450-\$900
Can I Still Drive?	:	Yes

What Does The Dodge B10BF Code Mean?

With the ignition on. Battery voltage greater than 10.4 volts. If the Totally Integrated Power Module (TIPM) detects a shorted high condition in the (N112) High Speed Radiator Fan Control circuit

What Are The Potential Causes Of The Dodge B10BF Code?

- (N112) HIGH SPEED RADIATOR FAN CONTROL CIRCUIT SHORTED TO BATTERY VOLTAGE
- RADIATOR FAN MOTOR
- TOTALLY INTEGRATED POWER MODULE (TIPM)

Reference Sources

[Dodge B10BF](#), DTCDECODE.