

DODGE B1888: POWER LIFTGATE PINCH SENSOR 1 CIRCUIT LOW

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$500
Can I Still Drive?	:	Yes (Short-term only)

What Does The Dodge B1888 Code Mean?

The Power Liftgate Module has detected the Left Liftgate Pinch Sensor circuit voltage is under 0.5 of a volt for over 20 seconds.

What Are The Potential Causes Of The Dodge B1888 Code?

- Left pinch sensor signal circuit faulty wiring
- Left liftgate pinch sensor
- Power liftgate module (PLGM)

Reference Sources

[Dodge B1888](#), DTCDECODE.