

## DODGE B1A68: STEERING COLUMN LOCK MODULE BOLT CONTROL LOW

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>Medium</div></div>       |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$100-\$900                        |
| Can I Still Drive?   | : | Yes                                |

### What Does The Dodge B1A68 Code Mean?

This code is set immediately when the Wireless Ignition Node detects the (F892) Ignition Switch Output circuit shorted to ground when the ignition key is removed.

### What Are The Potential Causes Of The Dodge B1A68 Code?

- (F892) IGNITION SWITCH OUTPUT (KEY-IN) CIRCUIT SHORTED TO GROUND
- STEERING COLUMN LOCK MODULE (ELV)
- WIRELESS IGNITION NODE (WIN)

### Reference Sources

[Dodge B1A68](#), DTCDECODE.