

## DODGE B2181: HEATED SEAT MODULE POWER SUPPLY LOW

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>Medium</div></div>       |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$250-\$350                        |
| Can I Still Drive?   | : | Yes                                |

### What Does The Dodge B2181 Code Mean?

With ignition on, if the Heated Seat Module (HSM) detects voltage under 10 volts on the (F937) Fused Ignition Switch Output (Run) circuit.

### What Are The Potential Causes Of The Dodge B2181 Code?

- Charging system voltage low
- (f937) fused ignition switch output (run) circuit
- Heated seat module (HSM)

### Reference Sources

[Dodge B2181](#), DTCDECODE.