

DODGE C1009: BRAKE FLUID LEVEL LOW

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$120
Can I Still Drive?	:	Yes

What Does The Dodge C1009 Code Mean?

With the ignition on and no system under voltage DTC present. This DTC will set if the brake fluid level switch indicates low brake fluid for 1 second

What Are The Potential Causes Of The Dodge C1009 Code?

- INTERMITTENT BRAKE FLUID LEVEL LOW DTC
- BRAKE FLUID LEVEL LOW
- (B20) BRAKE FLUID LEVEL SWITCH SENSE CIRCUIT SHORT TO GROUND
- (Z420) GROUND CIRCUIT OPEN OR HIGH RESISTANCE
- BRAKE FLUID LEVEL SENSOR
- ANTI-LOCK BRAKE MODULE

Reference Sources

[Dodge C1009](#), DTCDECODE.