

DODGE C1073: ABS PUMP MOTOR CONTROL CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$500-\$800
Can I Still Drive?	:	Yes

What Does The Dodge C1073 Code Mean?

The Anti-lock Brake Module (ABM) detects low pump motor feedback voltage with actuation of the pump motor relay

What Are The Potential Causes Of The Dodge C1073 Code?

- Blown pump fuse
- Wiring harness, terminal, connector damage
- (a921) high resistance in b+ circuits
- (z901) high resistance in ground circuits
- Integrated control unit

Reference Sources

[Dodge C1073](#), DTCDECODE.