

What Does The Dodge C1088 Code Mean?

With the ignition switch on, the Vehicle System Integration Module (VSIM) has detected the Brake Lamp Switch Sense circuit below a calibrated value.

What Are The Potential Causes Of The Dodge C1088 Code?

- (W512) brake lamp switch sense circuit shorted to ground
- Aftermarket light/siren controller
- Vehicle system integration module (VSIM)

Reference Sources

Dodge C1088, DTCDECODE.

