

What Does The Dodge C1089 Code Mean?

With the ignition switch on. The Vehicle System Integration Module (VSIM) has detected the Brake Lamp Switch Sense circuit above a calibrated value

What Are The Potential Causes Of The Dodge C1089 Code?

- (W512) BRAKE LAMP SWITCH SENSE CIRCUIT OPEN OR SHORTED TO VOLTAGE
- AFTERMARKET LIGHT/SIREN CONTROLLER
- VEHICLE SYSTEM INTEGRATION MODULE (VSIM)

Reference Sources

Dodge C1089, DTCDECODE.

