

DODGE P1009: HUMIDITY SENSOR MODULE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$60-\$200
Can I Still Drive?	:	Yes

What Does The Dodge P1009 Code Mean?

The Body Control Module (BCM) is the Local Interconnect Network (LIN) master for the Humidity Sensor. The Humidity Sensor detects humidity, dew point and windshield glass temperature, and sends this information to the BCM. The BCM then broadcasts the message over the Controller Area Network (CAN) data bus. The repair of this fault condition does not involve any external circuitry and centers on verifying the integrity of the internal circuitry and software validity.

What Are The Potential Causes Of The Dodge P1009 Code?

Humidity Sensor

Reference Sources

[Dodge P1009](#), DTCDECODE.