

## DODGE P1109: ELECTRONIC THROTTLE CONTROL - FORCED LIMITED RPM - BANK 2

### OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$350-\$500
Can I Still Drive?	:	No

### What Does The Dodge P1109 Code Mean?

With the throttle body powered and with no DTCs present which result in the throttle being shut or disabled. When the PCM detects a temporary excessive motor demand on Throttle Body 2. One trip fault. ETC light will flash.

### What Are The Potential Causes Of The Dodge P1109 Code?

- Obstruction in the throttle bore
- ETC motor/throttle body

### Reference Sources

[Dodge P1109](#), DTCDECODE.