

DODGE P1112: ELECTRONIC THROTTLE CONTROL - UNABLE TO OPEN - BANK 2

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$350-\$500
Can I Still Drive?	:	No

What Does The Dodge P1112 Code Mean?

During an End-of-Line throttle learn, service ETC Relearn and Spring test. When the PCM detects a failure of throttle body 2's plate to return to within a calibratable tolerance of its default position. Fault set when the throttle plate's actual default position is less than the expected default position. One trip fault. Three good trips to turn off the MIL.

What Are The Potential Causes Of The Dodge P1112 Code?

- Obstruction in the throttle bore
- ETC motor/throttle body
- Throttle plate jammed against the bore

Reference Sources

[Dodge P1112](#), DTCDECODE.