

Dodge P113E: O2 Sensor 2/1 Slow Response (High Frequency)

OVERVIEW

Severity

:

Medium

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$100-\$200

Can I Still Drive?

:

Yes

What Does The Dodge P113E Code Mean?

For an aged Upstream O2 Sensor, the response rate to the air/fuel change is slower than when it was new. The O2 Sensor tends to move less with the same air/fuel changes in a given time frame. Therefore by observing the activity of voltage readings from the Upstream O2 Sensor, the quality of the O2 Sensor can be detected.

What Are The Potential Causes Of The Dodge P113E Code?

- EXHAUST LEAK
- O2 SENSOR 2/1 SIGNAL CIRCUIT
- O2 SENSOR 2/1 RETURN CIRCUIT
- O2 SENSOR 2/1

Reference Sources

[Dodge P113E](#), DTCDECODE.