

DODGE P1217: ACTIVE EXHAUST VALVE 1 PERFORMANCE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$90-\$200
Can I Still Drive?	:	Yes

What Does The Dodge P1217 Code Mean?

The actual Active Exhaust Valve 1 Actuator position does not match the commanded position.

What Are The Potential Causes Of The Dodge P1217 Code?

- Mechanical butterfly valve seized
- Transmission spring broken
- Active exhaust valve 1 actuator

Reference Sources

[Dodge P1217](#), DTCDECODE.