

DODGE P1284: FUEL INJECTION PUMP BATTERY VOLTAGE OUT-OF-RANGE

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$220-\$1100
Can I Still Drive?	:	No

What Does The Dodge P1284 Code Mean?

Key on and the Fuel Pump Control Module (VP44) detected an invalid Low Idle Select signal from the PCM (ECM controller).

What Are The Potential Causes Of The Dodge P1284 Code?

Fuel injection pump is damaged or has failed

Reference Sources

[Dodge P1284](#), DTCDECODE.