

Dodge U1424: Implausible Engine Torque Signal Received

OVERVIEW

Severity

:

High

DIY Difficulty Level

:

Advanced

Repair Cost

:

\$500-\$1000

Can I Still Drive?

:

No

What Does The Dodge U1424 Code Mean?

Ignition on with system voltage between 9.0 and 16 volts. No PCM/ECM CAN Bus DTCs present. When the TCM receives an implausible engine torque signal from the PCM over the CAN Bus for a period of 1.0 second, this DTC will set.

What Are The Potential Causes Of The Dodge U1424 Code?

- FCM/TIPM CAN bus DTCs present
- Engine module DTCs present
- Powertrain control module
- Transmission control module

Reference Sources

[Dodge U1424](#), DTCDECODE.