

FORD B103B: THERMOELECTRIC DRIVER OVERCURRENT LOW

OVERVIEW

Severity	:	Low
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$70-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The Ford B103B Code Mean?

If SCME outputs to the driver seat backrest or cushion blower motor are shorted to ground or a blower motor resistance of less than 0.9 ohm is sensed, the SCME shuts down the driver seat system and sets this DTC.

Reference Sources

[B103B Pinpoint Test - 2008 Ford Truck Expedition 2WD V8-5.4L](#)