FORD B1600: PATS IGNITION KEY TRANSPONDER SIGNAL NOT RECEIVED

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$50-\$250

Can I Still Drive? : Yes (Short-term only)

What Does The Ford B1600 Code Mean?

Key on, and the PATS did not receive Ignition Key Transponder Signal was not received.

What Are The Potential Causes Of The Ford B1600 Code?

Refer to test procedures Section 419 of the Workshop Manual to determine why the Passive Antitheft System (PATS) did not receive the Ignition Key Transponder signal correctly.

Reference Sources

Pinpoint Test B

