

FORD B1681: PATS RECEIVER MODULE SIGNAL NOT RECEIVED

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$250
Can I Still Drive?	:	Yes

What Does The Ford B1681 Code Mean?

DTC B1681 (PATS Transceiver Module Signal Is Not Received) – sets when the PATS transceiver signal is not received by the IC. This DTC can be caused by circuits between the PATS transceiver and the IC, or circuits to the PATS transceiver. This can also be caused by using the incorrect PATS transceiver part number.

What Are The Potential Causes Of The Ford B1681 Code?

- Fuse
- Wiring, terminals or connectors
- PATS transceiver
- IC

Reference Sources

[Pinpoint Test E - 2008 Ford Truck Ranger 2WD L4-2.3L](#)