FORD B2103: ANTENNA NOT CONNECTED OVERVIEW Severity : Medium DIY Difficulty Level : Intermediate Repair Cost : \$50-\$250 Can I Still Drive? : Yes (Short-term only)

What Does The Ford B2103 Code Mean?

Key on, and the PATS detected that the Antenna was not connected.

What Are The Potential Causes Of The Ford B2103 Code?

Transceiver internal antenna damaged. Replace transceiver.

Reference Sources

PATS Job Aid Document - Motorcraft Service, B2103, page 2.

